
JOB HAZARD ANALYSIS

JOB: Liquid Nitrogen

DATE: 4/25/02

MODIFIED: 4/25/2002

PREPARED BY: Dave Mason

REVIEWED BY: Ellen Mecray

Recommended Protective Clothing and Equipment:
Cryo-gloves, safety goggles, boots, long pants

Sequence of Basic Job Steps	Potential Accidents/Hazards	Recommended Safe Job Procedures
Fill the small dewar with liquid nitrogen from the supply dewar	Splashing liquid nitrogen	Wear long pants, boots, eye protection, and cryo-gloves
Remove cover from large sample dewar	-	
Fill the large sample dewar from small dewar	Splashing liquid nitrogen	Wear long pants, boots, eye protection, and cryo-gloves
Replace dewar cover	-	-

U.S. Geological Survey
384 Woods Hole Rd.
Woods Hole, MA 02543